¼ Corner N ¼ Cor. Sec. 5 Quincy Twp 107-11
8/14/80 Set Cmt S ¼ 32 -108-11
#815804

Gov't notes, Sept 1853
Set Post for ¼ Cor

B.T.'s Burr Oak 6" S 3° E 40 links
Burr Oak 8" N 7° E 232 "

7-10-1980 (1980 Remon. BK) N. ¼ Cor 5 & Traverse nail shot here in 1979 gone but there was a ½" x 3" long piece of pipe down at the location. Dug with backhoe. In road appx 3½' deep found a 1" x 2" hub 2.45 West and 1.35 North of the ½" pipe location and a 1" x 2" hub and 120d spike 2.3 West of the ½" pipe location. Dug down to oldest road 6' deep and found a 1" x 2" hub 2.3 West and .1 South of the ½" pipe location. We found this road to be on bedrock 6.5 deep so we

did not dig further. From the ½" pipe we dug ___N, ___S. ___E, and ___West

½" pipe 10.34E 13.76N | 1"x2" hub 5½' deep 12.85E 12.66N | 12rod Spike 12.63E 13.9N | 1"x2" hub 6' deep 12.64E 14.04N

8-14-1980 Set a CIM over a ½"x18" rod over the oldest CHD hub found 6' deep 7-10-1980. The corner is 2' North of the ℄ of the road West and 4½' South of the ℄ of the road East, and 2' West of the ℄ Co. Rd. #10

RP's: C.S. Disc in pp #42896 SW 77.02
CS Disc in transmission pp. SE 60.58
Punch mark in N. end 36" Culvert WNW 101.53

See vertical file - Survey Data Range 11 for Klemachmidt Survey — Sec 32, T10S N, R11W. (1967)

4/89 DNR DIPPED CORNER, transmission pole SE Gone
Punch mark in culvert WNW N 82° W
CSD in P.P SW UP 3 3 ON SE side S 55° W