Section Corner N. Sec Cor. 5-6 Quincy 107-11
S. " 31-32-108-11
#813205

Gov't notes. Sept. 1853

Ref Post + stone chained stake, b. It mound with trench

11-15-1979 Dug here with the backhoe from 2' North of Kleinschmidt pipe, North 10', East 9', and West 6' by 4' deep



The conditions here are very poor with no natural black soil over the clay.

11-16-1979 Dug here again over Kleinschmidt pipe. Dug from the pipe West 2', East 7', South 2', and North into our previous diggings. We found only that someone had dug here about 3' in diameter into clay beneath Kleinschmidt pipe, the diggings being beneath an old road found about 2' deep and was not done when the pipe was set.

RP's to Kleinschmidt pipe:

Nail in telephone pole NNW 35.45

Nail in road W 27.0

Set pipe back.

8-14-80 Set a CIM over a ½" iron on the line from the N.¼ Cn 5 to the N.¼ Cn 6 and in line with the fence North according to DNR Traverse (fence now gone). Pulled pinched pipe from ℄ of the E-W road. The corner is 10' North of the ℄ E-W road and 2' West of the ℄ rd. South.

RP's: Spike in telephone pole North 24.95

CSD in pp # 32995 SE 47.63

CSD in telephone pole SW 46.77

4/20/89 DNR FD CIM DOWN 0.8' SPIKE IN T.P. N 8°W UP 3.8' ON EAST SIDE, NOW CUT OFF, CSD IN PP S 25°E UP 1.8' SW SIDE 47.69', T.P. S 24°W 46.80' NOW CUT OFF