8/11/92 Set CIC/P² at stake location

1/4 Corner 6-7 Farmington 108-13

Set by William Yerby 5-1857
West on Random between 6 & 7
35.50 Enter timber North & South
40.00 Set temp gr post
40.50 Begin to descend Bluff or Hill
44.50 Foot of same & begin to ascend Bluff or Hill
47.00 on top of hill or bluff.
76.80 Intersect West Boundary at post.
East on true line between Sec's 6 & 7
36.80 Set a gr Sec post from which
a Bur Oak 8 In in dia brs N 47½ W 22 14.52'
a " " 9 " " " " S 31¾ W 55 36.30'

8/11/92 County Surveyor dug at position of fence line intersect from west & N-S. Found wood stake piece 10" long leaning. dug out and cleared up farther down had mark with wood pieces in it running 6" into clean clay. There was a large post hole the south edge of it being ½' north of stake mark →

8/11/92 cont. the stake mark is ± 1' north & ± 1' west of the trav nail, we also dug at the prorated position 2' in all directions the clay was down ½' and clean. Note: this past Spring this area was grubbed & cleared to put in a new fence line, the ground doesn't appear to be disturbed very deep.
Set C.I.C. ½" at stake location 5' South of stub fence east & 1' west of N-S fence line. the corner lines with old fence west in woods RP's
CSD IN corner post NNE 4.66'
SPIKE; CSD IN twin 10" bur oak S65°W 32.33'
SPIKE; CSD IN 9" bur oak west 42.17'