8-3-83 : Set CIP

#831306 (1)

1/4 corner 13-14 Farm 108-13.
Set by William Verby 5-1854
9-1894 H Fraser P552 no 509 Lt. K Lamprecht.
found boulder stone what Mr Schully anered Mr Schacht
set in place of stake set by Hunter in a survey
left corner in place No Meas.

10-1875, 4-1877, 6-1888 Hunter P406 no 395
sections 12, 13, 14 centered around Poteau.
- used 1/4 corner for N-S lot line
- Meas north 39.76

June, 1867 H.E. Horton Pg. 85 No. 130 Shows 1/4 Cor
Meas. East 39.21 chs., Meas. North 39.76 Chs.

North between Sec. 13, 14

.50 leave "wet" Marsh bears NW

19.50 Enter "wet" Marsh bears NW & SE

25.00 leave " " " "

40.00 Set a qr sec post in mound of Earth and Sod. deposited Charcoal made trench & pits planted Osage Orange Seed E & W.

7-28-83, 1/4 Cor 13-14: Dug in center of N-S road from 4' South of t.n. (set in center of road and in line with fence East and West) to 5' North. Horton's (also recorded by Hunter) measure from 11-12-13-14 came 2.15 North of the t.n. Someone had dug at the South 2' of the hole, deep into clay and filled with tree bark. May be where tree ~~[illegible]~~ stump dug out. Found square mark (but no wood) along West side of (1st ~~hole~~) hole so continued digging West 0. Found sq. post mark with wood piece 4.2 West and .25 South of the t.n. Found

(2)

1/4 Corner 13-14 Farmington 108-13
#831306

7-28-83 continued: another square post mark with wood piece 3.9 West and 1.6 South of the t.n. Continued digging West and found a cedar post stub (2' long) 7.55 West and .10 North of the t.n. Dug to 7½' West of the t.n. by 4' deep at the West end of the hole. Good condition except in the diggings at the South end of hole. Dug East to 8' East of the t.n. Found pieces of bone and broken bottle in black hole in clay. Scraped down and found piece of charred wood and also found deep stake hole on North side of mark. Believe stone probably stood on top of glass and now gone. Drove 3' drill steel in stake hole as corner 6.17 East

and .41 North of the t.n. Did not have time to scrape this area but believe this to be recorded corner location. Hole 3' deep at East end and conditions still fair. Found glass at clay level. Black mark went down 1½' and stake hole 1½' deeper yet. t.n { E 13.02 / S 9.68 } corner

---

8-3-83, ¼ Cor 13-14; Set CIM over one 3' long drill steel driven 7-28-83. The corner is ± 6' East of ℄ and in line with fences East and West.

RP: CSD in pp# 2665 NNE 61.13
CSD in fence post East 67.74
CSD in corner post West 39.22