X 8-4-83 CTC/p2

#833506 (1)

1/4 corner 34-35 Farm 108-13

11-1877 Hunter P 324 No 318 S 34 a. Donke dug carfully & extensively for corner, found nothing. Mr Lindsley owns fence west and backfurrow east was placed from corner when standing.

- set stone 3x16x30 in line fence & center road
- 16 west set stone 2x8x16 set E&W with oak stake on north side M&L 19.98 3/4
- 16 south set stone 2x14x16 M&L 19.96
- 16 center of E 1/4 34 set oak stake with large boulder on south side at inters lower

10-1893 W Fraser P 536 No 498 S 33 & 34

A Earle - P Walker.

found stone in center road set by Hunter P 324

Co Hwy Dept. (1953±) B199 P 4 says 4"x6"x16" limestone with cross on top

found boulder, set 1" drill steel rivet set down 5 ins

Marker on steel fence post E 50.0

" " " " " W 50.0

Disc " " NW 58.56

" power pole E 50.17

6-1930 Co H D. B 58 P 35 found 1/16 stone south L.S.

Meas north 1317.5 to stone found - Meas south 1317.0

Meas ~~S~~ 2634.7 Meas N 2636.5

#833506 (2)

1/4 Corner 34-35 Farmington 108-13

set by William Kerby 5-1854

40.00 set a qr sec post in mound of Earth & Sod deposited charcoal made trench & pits planted Osage Orange Seed E & W.

6-14-83, 1/4 Cor. 34-35: Found CHD drill steel down 3" in ℄ N-S blacktop Co.R.11. Set concrete nail at road surface over iron as traverse point. Point in line with fence East.

RPs: Old CHD disc in wood fence post NW 59.06

CSD South side pp # 41913 E. 49.42

7-5-83, 1/4 Cor 34-35: Dug centered over drill steel shot here. Found it only 10" long. Found 34" drill steel down 16", ~~Set~~ .17 So. and ~~.13 West~~ .64 East of

traverse point. 34" drill steel stood at NE edge of a 4" x 13" x 14" limestone (down 30"). The stone has had its top broken off and the North edge is shattered so it could once have been the dimension given by Hunter. Set a 3/4" re-rod at the exact stone location and set the stone on the East side. Dug from the stone for 1'± West, 1'± East, 1'± South, and 3' North. Stone .58 South and .18 West of the traverse point.

8-4-83, 1/4 Cor 34-35: Set a CIC/P² at limestone location found 7-5-83. The cone is in the ℄ of the N-S road and in line with fence running East

RPS: CSD in pp # 41918 ENE 49.62

CHD disc in cn. post NW 59.31

1/4 Corner 34-35 Farmington 108-13 (3)
#833506

7-30-93 Set 1" SQ pipe w/cap [illegible] to P.K. Nail in P.P.
West of corner on South side of shared driveway
running west. Ref pipe w/cap is ±57 West of ℄
CR # 11 ℄ ± 16' So. of ℄ Driveway.

Δ @ Ref Pipe
To 1/4 cor 34-35
VA 89° 08' 30"
Slope 56.72 Hor 56.71

7-8-94 SET 1" SQ PIPE W/CAP IN ℄ CR 11 AT 1993 REFERENCE LOCATION RP's.

1" SQ PIPE W/CAP WEST 56.71

CSD IN PP # 41918 ENE 49.56

℄ DRIVEWAY WEST NORTH 17'