X

#1

#841806

1/4 corner west 1/4 18 Aronoco 108-14.
east 1/4 13 N Haven 108-15.

5-1891 Chas Fraser P451 No 435 L18.
Could not find corner or any evidence of it.
- run sec line set stake and stone by side.
M & L. 39.66.
-16 N set corner M & L 19.83.
sub-division corners in N 1/2 of NW 1/4 18.

4-1903 Charnsley. P49B L13 Shay Allis & others.
stone and stake shown on plat. no desc.
-16 north. stone M & L 19.82.

-over-

-16 south stake M & L 19.84 set 100 the west.
in river -
-16 west stake M & L 19.84.

4-1938 J Kerr. B12 P60. also p.54
found recorded boulder - no R.P.S. P.54 says Set boulder
-16 north set iron M & L 1307.72.
-16 center NW 1/4 18 set pipe 1201.69. east above 1/16.
then 1322.42. to pipe at 1/16 below center & N 1/4 18.
-16 east. corner (likely iron) at 11.99.17 then 1323.22
to center 18.

10-14-77 Dug from 1½' East of McGhie traverse nail East for 4', So. for 4' and N. 7' by 2' deep to clay. Found nothing.
10-77 Dug 3'x3' on N side c.p. @ double 1/16th N. Found nothing.
11-5-77 Set CIC/P² as the corner at the intersection of lines from ¼ Cor 13-14 over Center 13 and line from NE 13 over the 1/16th So (found).

1/4 Corner W 1/4 18 Oronoco 108-14 #841806
E 1/4 13 New Haven 108-15

11-5-77 (Cont.) Corner on E side of c.p. to fences N-S-W, .9E and .3N of tissue mail (also McKthie 1/16th North

10-14-77 Found a 3/4" punched pipe inside a 1 1/4" pipe .4'N and .5'E of McKthie corner and a 3/4" x 30" pointed shaft 2' East and 2.5'N of McKthie pipe

10-27-77 Dug with backhoe and found 5" x 10" x 26" limestone on the West side of old stake. Set pointed shaft found before in stake hole. Stake .3E and 1.05N of McKthie location (removed). Removed punched pipe also

11-5-77 Set 3/4" x 21" rod M&L by c.t.c. Corner

.35 E and .07 N of McAthie and .98 So and .05 E of stake found. Removed shaft from stake hole. Corner 4' So of ℄ and 1½' W of fence N+S

RP.'s Spike in E side sg. C.P. 55E 24.98
Spike with punch mark in E side pp# 37168
NNE 35.65