6-13-1967. set C/M over orig 1 3/8" x 30" iron bar
4-9-1974 - Reset 1" drill steel in B.t. S surface
#842209 (1)

1/4 corner center 22. Oronoco 108-14

No old records found but work done as proven by —
5-1941 J Kerr Power Dam survey. found 1/4" iron bar.
- Meas south to 1/4 22-27. 2620.3'
- Meas north to 1/4 15-22. ~~2620.3'~~ 2597.9
Corner. Iur .3' west of direct line.

6-1967. found iron shaft. 18" below road surface.
drove dap enough to set C/M over iron.
- Head of 20 D on NW side power pole near ground. NE 36.57.
- Dese on SW side power pole in school yard. -over-
with head at 20 D .1' south and lower. NNW 76.35

this iron found could have been set in caption survey
11-1894 p 555. earmarks of W Fraser work.

-16 south. set ½" x 24" rod M & L 1310.15
RP 1/16. bottle cap. power pole SSE 70.3.
" " SSW 59.3.
corner came nearly in center road - no fence -

1941 ties to Center 22.
SW corner main school building. WNW westerly 137.75.
NE corner wood shed. NNW Northwesterly 150.49.
Meas Center 22 west 2621.7 to rail line fence north ??? meas?

#842209 (2)

Card # 2. Center 22. Oronoco 108-14.

8-22-1969 removed C/M set ½" rod flush (grading) set no additional reference.

Co H D B 326 1968 found C/M Sta 131+19.61.

Meas south 2619.82

Meas west 2604.09 this doesn't jib with Rec meas 2621.7

4-9-1974 – found 5/8"x6" rod in Bit. Surf. dug with jack-hammer, found another rod and orig 1½" iron shaft. – Top of Shaft 2'8" deep – Set 1" drill Steel over 1½" shaft.

Corner is 1.3' West. of N-S ¼ line