1 ~~7-28-69 set C/M M&L.~~ #850108 #1
5-20-1975 Reset C/M M+L after finding. N-1-2
1/4 Corner North 1/4 1 New Haven 108-15 W Sec 36 Goodhue.
6-1902 Ch Armstrong P54B Meyer, Wright, Ahneman
Corner gone set limestone 6x10x16 M&L 39.96+.
-16 west. set temp point 19.98+ M&L.
-16 east found boulder M&L 19.98+.
-16 south set limestone 3x8x20 at 20.41 (1347.06'
then 19.94 1/4 (1316.2' to boulder at center 1
-16 center NE 1/4 1 set limestone 2x12x24.
found old corner under fence S87° W 9 lks 1 corner set not run according to law destroyed old corner.
-16 center NW 1/4 1. set limestone 4x12x14.
one.

at intersa of true lines
set witness corner 5' west of corner a granite boulder.
Marked witness corner. on east side size 5X11X14.

6-1969 J Kerr - meas line west from Twsp corner down middle road to guide corner search. 1st fence North 736.8 R 737.22 738.54
-2nd fence N 2066.7'. - set 120 & road at 2641.66
as Twsp corner was found 4.3 east 4.00 R 2637.4

120 lies center road 28.5' S to center tele pole in line fence S. ±
7-24-69 dug with tractor from 26 36 to 2650 on N½ road roadbed 2' deep can't probe. - soil below soft but nothing - run 1½ mile line found & road would be south of line if & at N¼ 2 correct. set nothing.
7-28-69 set C/M. M&L. twsp corners found and NW cor I ac set
2641.75
pepsi cap in power pole 3' E of S 30.3 } SE corner main house
center 3' elm. ESE 108.0 } 12' W of N 83.7

#2

¼ Corner N. ¼ 1 New Haven 108-15

#850108

5-19&20-75 After finding N 1-2 dug M&L but found nothing. Set C.I.M. on 5/8" x 12" rod M&L. Corner lies 1.7N and 2.90' E Kerr's C.I.M. location (Removed Kerr's C.I.M.) Corner 4' N & road, ½' E fence line south, and 21' south row of cottonwoods.

R.P.'s: Bottle Cap W. side power pole #931124 S. 31.72'

Center of huge elm ESE 105.3'

Eyeball of west side of house on N. side road. W. 49.0'