(1) 11-2-71 set 3.5' pipe fence post as corner, bears from east. 6/24/88 V.F. set 5/8" ROD OVER post with Dodge Co Alum Cap P.
section corner. West 6-7 New Haven 108-75
9-1882 Hunter P379 No 370 S6 H Druck and others.
Field Bk 5 P144
Corner missing - 2 E & T standing and stumps of N.E. and N.W. B Ts
- reset corner with short stake driven even with surface.
- meas east Record. 39.60 2613.6 actual 39.44 2603.04 #850605
set stake at 19.52 (1288.32 then 19.93 (1315.38 19.92 in field bk
To S 1/4 6 a corner reset from B trees.
witness to above 1/16 east 10" cherry S 53 1/2 W 23 1/2 lks.
(No Trees near here in 1976 RB)

Cap Mayon Pine Island.
found stone as corner.

(over

11-2-71 Co surv. ran line and meas from. 1/4 6-7, found; west on 3' ⑤ N found what blieved 1/16 corner replacement. (old concrete poured around corner post, long rotted away.). 1/16 at 1315.63 R 1315.38 8.3' N of ⑤ line. cont line west. dug entire area carefully for Hunters stake or Cap maxon stone, found neither. In edge plowed field. set 3.5' piece of steel fence post. as corner with glass & small stones. at 1288.57 R 1288.32 from 1/16 corner and. 13.6 South of ⑤ line. Came. 6' E, 4.5' N of Corner fence south. about 31' ENE of large tree,

#850605

(2) Section corner west 6-7 New Haven 108-15

Gov. Notes- Ball, Dep. Sur. Oct. 1853
North between 7 and 12.
63.50 Creek 50 lks. wide runs east.
68.20 Elm. 14 in.
80.00 Set corner post.
Elm 14 in. S1W 212 lks.
Aspen 10 in..N65W 20 lks.
Cherry 10 in. S9E 28 lkss.
Box Elder 10 in. N17E 16 lks.

6/24/88 Vince Fangman, fd fence post set as corner lowered & set 5/8" x18" smooth rod with Dodge County aluminum cap over top of fence post, corner ± 6' E of fence south, 4½' NORTH of E-W fence 16d spike in sw face of railroad t.e fence post ESE 11.70', 20d spike in 24" tree stump (struck by lightning) WSW 31.41, steel post as guard 1.0' South