1/4 Corner 8-9 New Haven #850906 108-15

(1)

8-20-1979 We dug from the traverse nail set in 1976 1.0 East and 1.5 South of the corner post North 1, West 5' and South 12½' by 3' deep into clay. We found a 6" square mark in clay 11.8 South and .5 West of the traverse nail. We followed the mark down about 1' into clay before it disappeared. We found a ¾" square by 10" drag tooth driven in clay .6 N and .2 West of the traverse nail and a hole of 2" to 3" diameter running well into clay 1.0 West of the drag tooth. There was a large boulder over the drag tooth which we removed. There

was about 1½' to 2' fill over the natural soil here and most of the boulder was up in the fill so we could not tell if it had been set or just pushed in by the corner post.

8-27-1979 Dug a small hole East of previous digging to cover the line from the Fence East at ¼ Cor T-8 over the fence at the 1/16th E, the fence at the Center 8, and the fence at the 1/16th East of the Center 8, which all lined up. and would project appx 6½' South of the drag tooth, more thoroughly but did not find anything. Set a CIC on a 5/8 pipe (sq) driven over the drag tooth found 8-20-1979. Corner 1.5 SE of corner post.

RP's: Spike and Disc in NE side of blazed 14" Black Oak NW 62.01
Spike and Disc in SW side of 10" blazed Black Oak WNW 66.35

#850906 (2)

¼ Cor. 8-9 New Haven Twp.

Gov. Notes- Cushing, Dept. Sur. 6-12-1854
North between sections 8 and 9,
40.00 Set quarter section post.
Aspen 8 in. N52E 12 lks.
Aspen 6 in. S72W 4 lks.