/ 8-7-89 C.H.D. SET 5/8" BRASS PLUG #853006 (1)

1/4 corner West 1/4 30 New Haven 108-15 & D Co line.
11-1874 Hunter P264 No 262 S 30 R Cornforth & others.
found remains of orig stake from notes of S E Bree
set boulder 7 x 9 x 16 in its place (No meas or adj. corners)

1-1896 Pr Fraser P589 No 535 S line W 1/4 18 S to W 1/4 30
for town board N. Haven twsp.
found boulder set P264 with Bree 8" Hook E 45 lks.
Taken in survey P471 No 452. to relocate S W cor 18 108-15
at that time (3-1892) meas from W 1/4 30 North 2 miles
short 163 lks making each 1/2 mile north short 40 3/4 lks
or 2613.1 at that time in survey P471.
— this exact line now re-run. Now 1306.635 (19.79 3/4)
2613.27 over

-16 North drove iron rod N & L 19.79 3/4 (1306.635'
To iron stake driven as corner on trav line and 1/4
distance of 2 miles W 1/4 30 north To W 1/4 18.

5-1910 Ch Larson P124B N 1/2 NW 1/4 30 Sam Closner.
If Plat drawn is 90° off or top of page is east than
W 1/4 30 corner found as hard head (also claimed by Hunter
and Jr Fraser – who drove iron rod north N & L 19.79 3/4 (1306.64
Larson 1/16 north drove iron stake N & L 19.82. (1308.12
pattern fits so survey platted with top of plat being east.
– Meas east on full mile E-W 1/16 line 38.27 - 2526.82
govt calls for 38.50 N side 30 38.19 S side but as Hunter
had east half north side 30 2637.72 not 40 chs then
38.27 could be reasonable mean meas without running line.

¼ Corner W.¼ 30 New Haven 108-15 (1)
#853006

Nov., 1978 Dodge Co. Surveyor, Ron Murphy, reports finding a boulder 1.0' x 0.8' x 1.0' down 2.5 feet .3 W and 2.2 So of of intersection. It was 2.7' to natural soil. He also says he found records that C. Larson found a boulder here in 1912 and set a 2"x6"x6" stone and stake @ the 1/16th So. C.L. Survey (1912) in Sec 25 108-16.

5-7-1980 (1980 Ramon. BK, Page 23) dug over iron (set by Murphy) found and shot in 1978. Found iron to be a 120d spike with twists. LRPs & CN 9.71 South CN 9.71 East Dug down and found the spike to be over a 8"x10"x15" boulder appx 2' deep. The top of the boulder was in the

old road and the base dug down into clay. Set boulder back and set spike back at road surface over stone. Corner 7½' North of fence line East, 4½ South of ℄ road West, and 1½' West ℄ N-S road.
RP's: Most E'ly NE Cr Home foundation (conc. block) SW 104.88
½" rod in center of road West (in line with center of large pole shed on South side of road West) W'ly 164.80
We only dug to verify stone – searched no further for anything else.

5-7-1980 (1980 Remon. BK, P. 24) 1/16th South: Dug with backhoe in line with fence West and in ℄ N-S road. Easily found 3"x6"x6" piece of limestone with remains of stake appx. 1.8 deep and just beneath surface of old road. Corner 1' N. fence line West and ½' West road ℄. This stone set by C. Larson. Dug no further. Set spike at surface LRP } 6.85 S / 6.75 E
RP: CSD NW side pp# 23204 NE 103.09
CSD SW side 22" pine on South side driveway East SE 130.98

104.29

1/4 corner West 1/4 30 New Haven 108-15 (3)

#853006

Gone N. 100,

40.00 Set quartz section post

Black Oak 18 S 89° E 38 lks

Black Oak 6 S 40° W 75

7-15-85, W 1/4 Cor 30: Corner may be destroyed by road construction
Found 1/2" rod set in center of road 164.8 Westerly in 1980
slightly bent. Replaced with 5/8" rod in same hole.
T @ 5/8" re-rod
mean. to W 1/4 Cor 30 (120d spike) = 164.82
x Rt W. edge brick chimney (bottom near roof) on older
house in farmyard North to W 1/4 30 = 94°16'18"
Additional R.P. to cor: Most E'ly NE corner of house Foundation
(just below siding) SW 104.78 Chord

8/7/89 C.H.D. SET 5/8" BRASS PLUG IN E C.R. #5 RP's

TOP NE COR OF STEP OF HOUSE SW 110.33'

SPIKE; DISC. IN SMALL TREE E 58.72'

SPIKE; DISC IN OAK NE 126.61'