S 1/4 Cor 35 109-13 ZUMBRO "933504"

5-12-76 Dug 20' E-W by 5' N-S by 2½' deep on ℄ E-W road. W. end of digging came 3'+ W. of full Govt measure from Twp. Mon. found E. Digging begin E of corner post on E side of driveway N. Condition good but found nothing.

5-14-76 Dug on N side of road. Found 4" x 4"/10" x 15" sandstone lying flat but

found black mark beneath extending 6" into clear clay. Also found possible (wood piece) stake hole. Reset stone over mark; scrap metal around stone and 1¼" X 2' pipe over stone

R.P.'s CSD W side of Asl ~~SE 45.05~~ gone 9-79

CSD fence post SW 43.0

steel post (at T) in concrete at NE corner of Quonset SE 178.27

steel post (at T) in concrete at NW corner of Quonset SE 157.65

CSD in power pole #32475 ENE 169.48

Punch hole in E end CMP to driveway S. ~~SE 66.48~~

5' N. center rd and 10' E. center driveway North gone 9-79