9433 04 (4)

S 1/4 Cor. 33, T109N, R14W (File with N. 3-4, Oronoco)

8-22-83, S 1/4 33: Attempted to dig for Raftis stake 052½ lks West of fence North but too close to old road coming in from SE and area was cut to clay.

(Oronoco BK A, pg 2)

9/14/1972 County Surveyor dug and found stake hole in yellow soil on the north side of large corner post to fences N-E. The stake hole was square and ran down to a point. Set a 1" x 6' pipe in stake hole up ± 1'
Rp's, pipe is ± 0.7' north of north edge of corner
Post ; ± 30' north of field road
chisel cross in cone. hdwall of small
cont→

943304

S¼ Cor. 33, T109N, R14W (File with N. 3-4, Oronoco)

8-22-83, S¼ 33: Attempted to dig for Raftin stake 52½' W. West of fence North but too close to old road coming in from SE and area was cut to clay.

(Oronoco BK A, Pg 2)

9/14/1972 County Surveyor dug and found stake hole in yellow soil on the north side of large corner post to fences N-E. The stake hole was square and ran down to a point. Set a 1" x 5' pipe in stake hole up ± 1'. RP's Pipe is ± 0.7' north of north edge of corner post & ± 30' north of field road ndwall of small chisel cross in conc.

cont →

Cont.
Culv. of field road west 51.95'